

Responder Knowledge Base

<https://www.rkb.us/>

Product Details

[Personal Protective Equipment \(PPE\)](#) \ [Clothing Items](#) \ [Gloves](#)



Blaze Fighter Glove

Blaze Fighter Glove Recall and loss of NFPA Certification:

THE GLOVE CORPORATION – BLAZE FIGHTER GLOVE

February 4, 2011: For Immediate Release

The Glove Corporation, a manufacturer of structural firefighting gloves and a participant in the SEI Certification Program, today notified SEI that it was discontinuing its manufacturing operations. Subsequent reports in the

On January 14, 2011, The Glove Corporation initiated a voluntary recall of one of its product lines, the Blaze Fighter glove. It issued a Safety Notice that was posted on SEI's website and, as reported by Mr. Allen Town, the company's president, e-mailed and faxed to over 180 of the product's distributors, over sixty percent of which are believed to have responded. The Glove Corporation contractually is required to continue those notification efforts and report on its progress until SEI is satisfied that all reasonable measures have been made to notify those affected, and that obligation continues in force even if the company has gone out of business.

The Glove Corporation has informed SEI that it is unable to replace or offer a refund for the gloves.

The Glove Corporation recalled the Blaze Fighter gloves after SEI's annual recertification testing determined that the product line did not comply with the applicable standard, the 2007 edition of NFPA 1971,

The Blaze Fighter gloves bearing these affected lot numbers can no longer be considered SEI-certified as compliant with the 2007 edition of the NFPA 1971 standard, or sold bearing the SEI certification mark.

New York Times and other publications have confirmed that the company has ceased doing business. Standard on Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting, specifically the Conductive Heat Resistance Test 1 found in Section 7.7.5 of that standard. These previously-scheduled tests were performed at the same time that SEI initiated an investigation in response to reports of firefighters receiving burns to the back of the hand while wearing this model glove. According to information provided by TGC in this investigation, the manufacturing change that altered the composition of the back of the glove is limited to gloves produced beginning in December 2009 bearing lot numbers 12109-12310.

GENERAL

Manufacturer: The Glove Corporation

Model Number: Blaze Fighter

Description

A true, 3-dimensional fire fighting glove with goatskin/military grade Kevlar outer, goatskin forchettes, Sentinel breathable vapor barrier and modacrylic FR liner. Glove construction includes our unique GLOVE BOND adhesive system that eliminates liner pull out.

Protective Application(s)

not provided

Part Number: blaze fighter

Availability: In stock

Availability Notes: not provided

MSRP: Contact Manufacturer

Information Provided By:

The Glove Corporation
301 N Harrison St
Alexandria, Indiana 46001
UNITED STATES

Phone: 800-346-4253

Email: mlittle@glovecorp.com

Website: www.glovecorp.com

Page Last Updated: September 30, 2008

Additional Information

- [Blaze Fighter Glove](#)



Blaze Fighter Glove

SPECIAL REQUIREMENTS

Description of Warranty: Normal service life

Do gloves contain latex?: No

Do gloves contain other known allergens?: No

Is Material Safety Data Sheet (MSDS) available for materials or components of gloves: not provided

Knowledge Links

[No third-party certifications in the RKB](#)

[Related Safety Notices](#)



Reference herein to any specific commercial products, processes, or services by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government. Neither the United States Government nor any of its employees make any warranty, express or implied, including but not limited to the warranties of merchantability and fitness for a particular purpose for any specific commercial product, process, or service referenced herein.
RKB Version 3.10 (February 2011) Copyright © 2003-2011 DHSFEMA